Victor



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

1135570 - R8 SDMS

1595 Wynkoop Street
DENVER, CO 80202-1129
Phone 800-227-8917
http://www.epa.gov/region08

August 27, 2009

Mr. Paul Rumelhart Kootenai Business Park Industrial District P.O. Box 1071 Libby, MT 59923

Subject:

Libby Asbestos Superfund Site

Operable Unit 5 – Former Stimson Lumber Property

Wood Chip Piles

Dear Paul:

You recently asked the U.S. Environmental Protection Agency to provide you with any available data we have related to the wood chip piles on the Former Stimson Lumber property, Operable Unit 5 of the Libby Asbestos Superfund Site.

In 2007, EPA collected a number of bulk samples from the top, middle, and bottom sections of the wood chip piles. Figure 2-7 (enclosed) shows the locations where samples were collected. Twenty (20) samples were analyzed qualitatively for Libby Asbestos (LA) using both Polarized Light Microscopy (PLM) and Transmission Electron Microscopy (TEM).

Using the PLM method, one of the samples contained a measurable concentration of Libby Asbestos. Libby Asbestos was not detected in any of the remaining 19 samples. Table 2-9 (enclosed) provides a summary of all bulk material sample results from this investigation.

Using the TEM method, four samples contained a measurable concentration of Libby Asbestos. Libby Asbestos was not detected in any of the remaining 16 samples. Table 2-10 (enclosed) provides a summary of all bulk material sample results from this investigation. Please note that we were not able to determine the LA concentration in the samples where LA was observed, only that LA was present.

Twelve (12) personal air samples were collected from the excavator operator and the sample collection personnel during the wood chip sampling activity. LA was not detected in any of the personal air samples. Table 2-11 (enclosed) provides a summary of all personal air sample results from this investigation. Please note that water suppression was used during the sampling effort due to fugitive dust emissions and our inability to restrict access to areas adjacent to the piles.

If you need any further information, please call me at (303) 312-6552.

Thomas

Sincerely,

Rebecca J. Thomas Project Manager

Enclosures

cc:

Victor Ketellapper, EPR-SR

David Berry, EPR-SR




Table 2-9. Wood Chip Pile Bulk Material Sample Results - PLM-9002 Analysis

| | Property Group | | | | Sample | Location Description | | Media | Analytica | Results |
|--------------------------|------------------------------------|-------------|-----------------|--------------|----------------------|------------------------------------|--|-------|-------------|---------|
| Sample ID | (Location) | Sample Date | Category | Matrix | Group | (Sub Location) | Field Comments | Type | Method | LA (%) |
| SL-70122-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-1, top 1-2ft | Bulk | PLM-9002 | ND |
| SL-70135-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-5, middle 3-4ft | Bulk | PLM-9002 | ND |
| SL-70139-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-10, boltom 7-8ft | Bulk | PLM-9002 | ND |
| SL-70143-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-9, middle 3-4ft | Bulk | PLM-9002 | ND |
| SL-70145-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-9, bottom 6-7ft | Bulk | PLM-9002 | ND |
| SL-70159-C | 875 Highway 2 S | 10/10/2007 | Field Sample | Wood Chips | Property | Wood chip piles | D-C-6, middle 4-5ft | Bulk | PLM-9002 | ND |
| SL-70168-C | 875 Highway 2 S | 10/11/2007 | Field Sample | Wood Chips | Property | Wood Chips | D-C-12, top 1-2ft | Bulk | PLM-9002 | ND |
| SL-70173-C | 875 Highway 2 S | 10/11/2007 | Field Duplicate | Wood Chips | Property | Wood Chips | D-C-16, top 0-1ft | Bulk | PLM-9002 | ND |
| SL-70177-C | 875 Highway 2 S | 10/11/2007 | Field Sample | . Wood Chips | Property | Wood Chips | D-C-17, middle 3-4ft | Bulk | PLM-9002 | ND |
| 01.70404.0 | 075 History 0 C | | | | | Mand Object | D-C-20, top 1-2ft; Debris pile with some rocks, 30% soil, 70% wood chips | Bulk | PLM-9002 | DETECT |
| SL-70184-C | 875 Highway 2 S | 10/11/2007 | Field Sample | Wood Chips | Property | Wood Chips Wood Chips | D-C-19, bottom 6-8ft | Bulk | PLM-9002 | ND |
| SL-70189-C SL-70193-C | 875 Highway 2 S | 10/11/2007 | Field Sample | Wood Chips | Property | Wood chip pile | D-C-34, top 1-2ft | Bulk | PLM-9002 | ND |
| SL-70193-C SL-70199-C | 875 Highway 2 S 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | Property Property | Wood chip pile | D-C-34, top 1-2it | Bulk | PLM-9002 | ND |
| SL-70199-C SL-70203-C | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | | Wood chip pile | D-C-31, bollon 6-71 | Bulk | PLM-9002 | ND |
| SL-70203-C SL-70211-C | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | Property Property | Wood chip pile | D-C-29, bottom 4.5-5ft | Bulk | PLM-9002 | ND ND |
| | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | | Wood chip pile | D-C-25, middle 2-3ft | Bulk | PLM-9002 | ND |
| SL-70216-C | 673 Fighway 23 | 10/12/2007 | Field Sample | Wood Chips | Property | vvood criip plie | D-C-24, bottom of exposed | Duik | F LIVI-3002 | NO - |
| SL-70220-C | · 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | Property | Wood chip pile | bank 7-8ft | Bulk | PLM-9002 | ND |
| SL-70227-C | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | Property | Wood chip pile | D-C-21, middle 4-5ft | Bulk | PLM-9002 | ND |
| SL-70231-C | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips | Property | Wood chip pile | D-C-23, 8-9ft | Bulk | PLM-9002 | ND |
| SL-70234-C | 875 Highway 2 S | 10/12/2007 | Field Sample | Wood Chips' | Property | Wood chip pile | D-C-27, 3-4ft | Bulk | PLM-9002 | ND |

Notes and Definitions:

The report excludes all lab quality control results, such as those associated with Lab Blanks, Lab Duplicates, Re-Preparation, Re-count Same, Re-count Different, Verified Analysis, etc. PLM = polarized light microscopy

LA = Libby Amphibole

ND = non-detect

% = percent

C = Chrysotile

< = less than

Table 2-10. Wood Chip Pile Bulk Material Sample Results - TEM Analysis

| | | | | · | , | | | | Method - | ISO 10312 |
|------------|-----------------|-------------|--------------|----------------------|--|--------|------------|-----------------|----------|------------|
| | Property Group | | | Location Description | | Media | | | Grid | Total Cond |
| Sample ID | (Location) | Sample Date | Sample Group | (Sub Location) | Field Comments | Type | Matrix | Category | Openings | LA |
| SL-70122 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | D-C-1, top 1-2ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70135 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | D-C-5, middle 3-4ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70139 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | D-C-10, bottom 7-8ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70143 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | D-C-9, middle 3-4ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70145 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | D-C-9, bottom 6-7ft | Bulk | Wood Chips | Field Sample | 10 | · ND |
| SL-70159 | 875 Highway 2 S | 10/10/2007 | Property | Wood chip piles | D-C-6, middle 4-5ft | Bulk | Wood Chips | Field Sample | · 10 | ND |
| SL-70168 | 875 Highway 2 S | 10/11/2007 | Property | Wood chip piles | D-C-12, top 1-2ft | Bulk . | Wood Chips | Field Sample | 10 | DETECT |
| SL-70173 | 875 Highway 2 S | 10/11/2007 | Property | Wood chip piles | D-C-16, top 0-1ft | Bulk | Wood Chips | Field Duplicate | 10 | ND |
| SL-70177 | 875 Highway 2 S | 10/11/2007 | Property | Wood chip piles | D-C-17, middle 3-4ft | Bulk | Wood Chips | Field Sample | . 10 | ND |
| SL-70184 | 875 Highway 2 S | 10/11/2007 | Property | Wood chip piles | D-C-20, top 1-2ft; Debris pile with some rocks, 30% soil, 70% wood chips | Bulk | Wood Chips | Field Sample | 5 | DETECT |
| SL-70189 | 875 Highway 2 S | 10/11/2007 | Property | Wood chip piles | D-C-19, bottom 6-8ft | Bulk | Wood Chips | Field Sample | 10 | ND. |
| SL-70193 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-34, top 1-2ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70199 | 875 Highway 2 S | 10/12/2007 | Property · | Wood chip pile | D-C-31, bottom 6-7ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70203 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-32, middle 1-1.5ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70211 · | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-29, boltom 4.5-5ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70216 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-25, middle 2-3ft | Bulk | Wood Chips | Field Sample | 10 . | ND |
| SL-70220 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-24, bottom of exposed bank 7-8ft | Bulk | Wood Chips | Field Sample | 10 | ND |
| SL-70227 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-21, middle 4-5ft | Bulk | Wood Chips | Field Sample | 10 | DETECT |
| SL-70231 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-23, 8-9ft | Bulk | Wood Chips | Field Sample | 10 | DETECT |
| SL-70234 | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | D-C-27, 3-4ft | Bulk | Wood Chips | Field Sample - | 10 | NĐ |

Notes and Definitions:

The report excludes all lab quality control results, such as those associated with Lab Blanks, Lab Duplicates, Re-Preparation, Re-count Same, Re-count Different, Verified Analysis, etc.

LA = Libby Amphibole

C = Chrysotile

. ND = Non Detect

Table 2-11. Wood Chip Pile Personal Air Sample Results

| [| | | | | - | T | | | | l | Analytical Results (METHOD - ISO 10312) (Air = structures/co(Dust = structures/cm2) | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------|---------------|-----------------|------------|----------|----------------|-------|---------|----------|--------------|--------------|---|--------------------------|-------|-------------------------|--------|-------------------------|--------------|----------|----------|--------------|------------------|------------------|-------------|---------------------|----------------------|-----|------------|----------|------------------|-------------------------|--------|------------------|------|-----|---------------|----------|--|---------|-------|
| i | | | | | l | l | 1 | ı | | 1 | ~ | Libby Araphiboles (LA) | | | | | | | | | Chrysottle (C) | | | | | | | | | Other Amphiboles (OA) | | | | | | | | | |
| 1 | | | ł 1 | 1 | 1 | l | ì | ı | | | | Excluded Structures | | | | | res Detected | | | Excluded 8tm | | luded Structures | | Structures Detected | | 7 | 1 | Exch | ded Struct | | | uctures Detected | | T | $\overline{}$ | | | | |
| j | | | | | Location | Į. | 1 | ı | | Vol (air=L)/ | | Aspect Length < Dia- | | Aspect Length < Dia- Le | | Aspect Length < Dia- Le | | | | | | Total | Total Total | | Aspect Length < Dia- | | Length 0.5 | Length 6 | enoth 6 Length > | | Total | Aspect | | | | Length & | | > Total | Total |
| 1 | į . | Property Group | Sample | Sample | Description | Media | i . | Sample | 1 | Area | Grid | Ratio < | 0.5 u | meter > | to 5 u | to 10 u | | Conc. LA | Count LA | Ratio | 0.5 u | meter > | to 5 u | to 10 u | 10 u | | Count C | | 0.5 u | meter > | to 5 a | to 10 u | 10 u | | | | | | |
| Sample iD | Yask | (Location) | Date | Group | (Sub Location) | Type | Matrix | Type | Category | (dust=cm²) | Openings | 5:1 | | 0.50 | | 1 | | | | < 5:1 | 1 | 0,5u | 1 | | 1 | 1 | 1 | < 5:1 | 1 1 | 0.5u | 1 | 1 | 1 | OA | QA. | | | | |
| | Soll Sampling | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | Alt | Outdoor | Personal | Field Sample | 316 | 95 | 6 | 1 0 | 0 | 0 | 1 0 | 0 | 1 0 | 0 | 0 | 0 | 1 0 | 0 | 0 | 0 | 1 0 | 0 | 0 | T 0 | 0 | ٥ | 1 0 | 0 | 1 0 | 1 8 | | | | |
| SL-70121 | Operator | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | Air | Outdoor | Personal | Field Sample | 311 | 100 | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 10 | - | | | | |
| SL-70140 | Operator | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | N# | Outdoor | Personal | Field Sample | 418 | 75 | 0 | 0 | 0 | 1 0 | 0 | 0 | 0 | ٥ | .0 | 10 | 0 | - 0 | 0 | 0 | 0 | 0 | - | 0 | | 0 | - | 0 | 1 0 | - | | | | |
| 81-70141 | Soil Sampling | 875 Highway 2 S | 10/10/2007 | Property | Wood chip pile | Air | Outdoor | Personal | Field Sample | 437 | 75 | 0 | 0 | 0 | 0 | 0 | 0 | . 0 | . 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | • | 0 | 7 0 | | | | | |
| SL-70163 | Sof Sampling | 675 Highway 2 S | 10/11/2007 | Property | Wood thip pile | A# | Outdoor | Personal | Field Semple | 330 | 90 | 0_ | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | . 0 | 0 | 0 | 7 0 | 0 | | | | |
| SL-70164 | Operator | 875 Highway 2 S | 10/11/2007 | Property | Wood chip pile | Alt | Outdoor | Personal | Fluid Bample | 328 | 85 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | .0 | 0 | | - | 0 | 0 | 0 | 0 | 0 | . 0 | 0 | | 0 | 0 | 0 | 10 | 0 | | | | |
| SL-70182 | Soil Sampling | 875 Highway 2 S | 10/11/2007 | Property | Wood chip pile | Au | Outdoor | Personal | Field Sample | 140 | 100 | 0 | 0 | . 0 | . 0 | 10 | . 0 | 0 | 0 | 0 | 0 | ٥ | . 0 | 0 | 0 | T 0 | 0 | | 0. | 0 | 0 | 0 | 0 | 0 | 10 | | | | |
| SL-70183 | Operator | 875 Highway 2 S | 10/11/2007 | Property | Wood chip pile | Alt | Outdoor | Personal | Fleid Sample | 155 | 100 | _ 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0_ | _ 0 | ٥ | 0 | .0 | l0 . | 0_ | _ 0 | | 0 | ' | . 0 . | 9 | 0 | 10 | | | | | |
| 8L-70190 | Sampling | 875 Highway 2 S | 10/12/2007 | Property | Wood chip pile | , Air | Outdoor | Personel | Field Sample | 382 | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | Ð | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | Ö | 0 | • | 0 | T 0 | | | | | |
| SL-70191 | Operator | 875 Highway 2 S | 10/12/2007 | Property | Wood Chip Pile | Air | Outdoor | Personal | Field Sample | 365 | 60 | 0 | 0 | 0 | 0 | Q | 0 | 0 | 0 | 0 | 0 | 0 | 0 | . 0 | 0 | 0 | 0 | . 0 | 0 | . 0 | 0 | 0 | 0 | 0 | 0 | | | | |
| SL-70221 | Sampling | 875 Highway 2 S | 10/12/2007 | Property | Wood Chip Pile | Aje | Outdeor | Personal | Field Sample | 173 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | _ 0 | 0 | 0 | 0 | 0 | . 0 | 0 | _ 0_ | 0 | | | 0 | 0 | | | | |
| SL-70222 | Operator | 875 Highway 2 S | 10/12/2007 | Property | Wood Chip Pile | Alt | Outdoor | Personal | Field Sample | 208 | 100 | 0 | . 0 | 0 | 0 | 0 | 0 | 0 | 0 | Ö | 0 | 0 | 0 | 0 | 0 | 0 | . 0 | . 0 | 0 | 0 7 | 0 | 0 | 0 | 1 0 | 0 | | | | |

Notes and Definitions:
The report excludes all lab quality control results, such as those associated with Lab Blants, Lab Duplicates, Re-Preparation, Re-count Same, Re-count Different, Verified Analysis, etc.

N/A = not applicable

L = librar cm² = square centimeter 6/cc = Structures per cubic centimeter 8/cm² = Structures per square centimeter

LA = Libby Amphibole

C = Chrysotile GA = Other Amphibole < = less than
u = micron
> = greater than